DESCRIPTION QUANTITY RATE AMOUNT 1 Supply and Install of double door 1511mm x 2035mm Trellidor/similar security No 1 Image: Comparison of the comparison of th
burglar with locking system No 1 2 Supply and Install of 1800BTU Air Conditioner No 1 3 Supply and Install of 127mm width window blinds (Chocolet brown) m ² 6 4 Painting work on wall : One under coat and two coats Plascon Micatex paint on wall (orange). m ² 50 5 Supply and install of 1.5m x 0.65m x 25mm thick white melamine carboard door for buildin air conditioning system m ² 1.5
3 Supply and Install of 127mm width window blinds (Chocolet brown) m ² 6 4 Painting work on wall : One under coat and two coats Plascon Micatex paint on wall (orange). m ² 50 5 Supply and install of 1.5m x 0.65m x 25mm thick white melamine carboard door for buildin air conditioning system m ² 1.5
4 Painting work on wall : One under coat and two coats Plascon Micatex paint m ² 50 5 on wall (orange). 5 Supply and install of 1.5m x 0.65m x 25mm thick white melamine carboard door m ² 1.5 5 Supply and install of 1.5m x 0.65m x 25mm thick white melamine carboard door m ² 1.5
on wall (orange). 5 Supply and install of 1.5m x 0.65m x 25mm thick white melamine carboard door m ² 1.5 for buildin air conditioning system
for buildin air conditioning system
6 Supply and install of 120mm x 690mm trucking cover for electrical and Network cab m ² 0.5

SUMMARY FOR SHEDULE OF QUANTITIES FOR THE COUNCILLOR'S RESOURCE CENTRE

SECTION 1: REPAIR WORK	-
SUBTOTAL	-
VAT 14%	-
TOTAL	-